



JON M. HUNTSMAN, JR.
Governor
GARY R. HERBERT
Lieutenant Governor

State of Utah
DEPARTMENT OF NATURAL RESOURCES
Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Supervisor DRH

Inspection Report
Minerals Regulatory Program
Report Date: May 16, 2005

Mine Name: Highland Mist
Operator or Permittee Name:
Anasazi Gold

Permittee Mailing Address:
472 North Main Street
Kaysville, Utah 84037

Inspector(s): Doug Jensen

Other Participants: None

Permit Status: Proposed
Current Acreages:
Total Permitted (Bonded): 4 acres
Total Disturbed: N/A

Permit number: S/021/035
Inspection Date: April 25, 2005

Weather: Cool, rain & snow
Inspection Start Time: 2:15 PM
Inspection End Time: 2:45 PM
Site location/Area Inspected (i.e. Pit #):
Proposed Site
Surface Ownership: SITLA
Mineral Ownership: SITLA
Mineral Mined: Gold, Silver
Type of Mine: Pit

Elements of Inspection	Evaluated	N/A	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (open shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Explosives, magazines	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Deleterious Material	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Concurrent Reclamation	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Erosion Control	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Demolition	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Backfilling and Grading (trenches, pits, roads, highwalls, shafts, drill holes)	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Water Impoundments	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Soils	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. Revegetation	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14. Air Quality	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. Facilities	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16. Other	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Inspection Date: April 25, 2005; Report Date: May 16, 2005
Page 2 of 2
S/021/035

Purpose of Inspection:

Checked the site while in the vicinity.

Inspection Summary:

Checking the site prior to approval of the permit. There have been no changes to the site since my last inspection. Photos were taken and are included in this report.

Directions to the site:

See previous inspection memo dated June 8, 2004.

GPS data:

None gathered

Inspector's Signature

A handwritten signature in cursive script, appearing to read "Doug Jensen", written over a horizontal line.

Date: May 16, 2005

dj:jb

Enclosures:

cc: North American Holding, Inc.
Will Stokes, SITLA

O:\M021-Iron\S0210035-HighlandMist\inspections\04252005insp.doc



DSCN0138.JPG 2005/04/25 14:13:13



DSCN0139.JPG 2005/04/25 14:13:18